FSH Annual Meeting

October 31, 2016



Selling Price per Square Foot



RESIDENT MIX

70% Owners 30% Renters



FSH Board GOALS

- 1. Ensure the financial viability and financial integrity of the FSH
- 2. Maintain the physical facility
- 3. Ensure safety, cleanliness and livability for the residents
- 4. Govern within the Master Deed, By-laws and Rules/Regulations
- 5. Ensure effective and efficient operation of the building
- 6. Upgrade the physical facility, when feasible within FSHA budgetary constraints

2016 has been.....

Very busy

Stressful

Upsetting to some

Productive

Hurricane Matthew



Mold Remediation Project—Pouring New Basement Concrete Floor



Mold Remediation: Dehumidifiers



Mold Remediation: Dry Vent



Elevator Modernization

- Elevators last modernized in 1968 with expected life of 25 years
- "Call" will be faster
- Precise leveling
- Controlled door motion
- Fewer breakdowns
- Remote monitoring
- Safer
- Less electricity use
- Will have parts
- Better-looking interior
- Increased perceived value of the building


1968 Elevator Controller



A Crane Lifts New Elevator Controllers and Motors to the Roof




2016 Elevator Controller



New Motor for Elevator



New Interior for Elevator




Shed Roof


Covers HVAC equipment, workshop, bike room—was leaking




Leaks Under the Shed Roof



New Shed Roof in Progress



Shed Roof (finished)



Water-Proofing Roofs/Terraces

starts with removing planters, etc



Railing were Removed—Water and Rust in the Hollow Tube



Water Under the Old Protective Membrane Causing Leaks



Leveling Low Spots



Applying Water-Proofing Material



Finished Surface



Terrace Doors Were Another Source of Leaks






Looking Down—Under the Door Sill---Gap between Concrete and Wood is another Source of Leaks



Murray Ave Terrace Doors with Water-Proofing







Rebuilt Domestic Water Pump (need one more)




New Treads on Loading Dock Ramp




New Security on Back Door



New Insulation on Chill Water Pipes



New Shower at Pool



Other Projects completed this year

- Replace window sash
- Spring cleaning
- Uniforms for staff
- Created new financial reports using Quickbooks
- Partial financial audit

FUTURE PROJECTS: Pool & Surround Need to be Resurfaced



Pool Fence Needs Repair/Replace



Wood Outside Windows Needs Repair or Replacement



Chandelier Needs to be Rewired/Replaced




Other Future Projects

- Repair and replaster ceilings and walls damaged by leaks
- Paint wainscot, walls, halls, stairwells
- Digital meters
- Light pole and shade for pool
- Pool furniture
- Resurface top roof
- Recoat stucco outer walls of building

Future Enhancements

- Resurface and landscape parking lots
- New fence from pool to end of property with gate
- Gate for S. Battery parking lot
- Enlarge and enhance workout room



AREA CALCULATIONS


OTAL APELING ELECTION AND MEDIT 1819 5071

ORD VIOLENCE OF COMPOSIT


SON PHACE WORDST

PROPOSED SITE PLAN


KING STREET




KING STREET




KING STREET







2 1/2" 15'-8" PLAN (FLATENED) AWNING SUPPORT AWNING DETAILS
scale= 1/4"= 1'-0"




5 DOOR ELEVATIONS
Scalo= 1/4"= 1'-0"











CURRENT PHOTOGRAPH



HISTORICAL PHOTOGRAPHS



